
## Licenced Premissis Plan



REINSTATEMENT / DEMOLITION PLAN LEGEND: Indicates extent of existing building areas / elements to be demolished or removed to allow for reinstatement and structural upgrade Existing 150mm thick (1650mm high) concrete foundation walls to Exterior: Existing timber framed (100x75mm) timber bevel back weather board exterior walls + plaster board linings to interior Interior: Existing timber framed (100x75mm) plater board lined Refurbished / Replaced existing windows - Refer to DT7.0 Reduced Finished Floor Levels **General Demolition Notes** Clean and seal all smoke stained framing timbers to be retained Remove all interior wall and ceiling linings and replace with new, investigate potential damage to framing timbers, replace those damaged by fire and smoke seal remaining framing members

• Replace timber windows where damaged by fire - Refer DT7.0 Refurbish windows / reglazing damaged windows where noted. Clean and seal all smoke stained joinery framing to interior

· Check ceiling / roof framing for fire damage. Replace framing consistent with structural

 Remove and replace all floor coverings including vinyl flooring and carpet
 Replace all plumbing fittings and fixtures in existing locations to toilets and change areas, Replace pipe work / connections where heat affected or unable to be cleaned successfully · Refurbish and Re-finish all wall linings and built in fixtures within areas unaltered by structural

Remove fixed bench seating and allow for reinstatement with new

reinstatement, consistent with repair of all smoke damage Replace interior doors / hardware and re-finish where damaged by fire

Clean, seal and paint all concrete foundation walls

upgrade and smoke seal remaining framing

15 November 2021 Wellington City Council void

M104

Lyall Bay Parade Wellington

Maranui Surf Club

Fire Reinstatement and Structural Upgrade Exisiting Upper Level / Demolition Plan

DI